
Instructions for transport partners - Transport of goods from the steel industry -

For the transport of goods from the steel industry you have to consider:

1. The drivers have to be trained for steel transports.
2. At every transport each driver has to carry his personal protective equipment. This includes: Helmet, safety shoes, reflective vest, work gloves, trousers.
3. You have to have a permanent special authorisation according to § 46 para. 1, no. 5 und § 46 para. 1, no. 2 StVO (German road traffic regulations) for transports with excess width, excess height and / or excess length on motorways and highways.
4. Before starting the tour, the drivers have to check if enough equipment for load securing is in the truck respectively in the trailer. Enough equipment is:
 - ✓ 20 tension belts 5000 daN with long lever ratchet spanners
 - ✓ 2 clamping planks
 - ✓ 40 corner protector
 - ✓ 40 anti-slipping mats

If the quantity or the functionality of the load securing is insufficient, your driver has to inform the dispatching department from Meyer & Meyer immediately.

5. If you are using your own equipment, you have to supply the equipment for load securing, which is mentioned in point 4:

Furthermore the trailers have to fulfil the following technical properties:

- ✓ Edscha roof for loading by crane
- ✓ Coil tray
- ✓ 4 pluck stakes on every side
- ✓ Side slats made of aluminium
- ✓ Certificates to DIN EN 12642 (Code XL)

